## GARY R. HERBERT Governor GREGORY S. BELL

Lieutenant Governor

## State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining JOHN R. BAZA

Division Director

## **Minerals Inspection Report**

	191	18	9
Reviewed	41	11	/

Report	Date: 04/08/201	5		
Mine Name: Drumbeat #1,2,3,4	Permit Number:	S/023/0089	Mine Status:	Active
Operator Name: Bradley Jones/Jones Landscaping	Inspection Date:	04/03/2015	Permit Fees:	Paid
Inspector(s): Wayne Western	Inspection Time:	1:00 - 1:30 pm	Bond Amount:	\$20,700
Attendee(s): none	Weather:	sunny - mild	Bond Escalation:	04/19/2013
Inspection Purpose: Routine inspection			Prior Inspection:	10/01/2014
Conclusions and Recommendations The Division has received unconfirmed reports that there is evidence of explosive use. The disturbances were shallow The permit fees have been paid. The bond is adequate to confirmed reports.	and there were no blast h	noles in the pits.		

The permit fees have been paid. The bond is adequate to complete reclamation. The annual report was not submitted. The Division assumes that if not annual report is received then no production occurred. The last time production was reported was for 2008.

There was no	activity	at the	site during	the	inspection.
--------------	----------	--------	-------------	-----	-------------

<b>Elements of Inspection</b>		Evaluated & Commented	Enforcement		
1.	Permits, Revisions, Transfer, Bonds				
	The permit fees for 2015 were paid. The bond is adequate for reclamation.  The last annual report was for 2008 (Dale Rogers). The permit was transferred to Brad Jones in 2011. Without an annual report the Division assumes that there was no production unless there is evidence of production. If no production occurs in 2015 then the Division could require reclamation.  The Operator does not have a sales or lease contract with the BLM. Therefore, the BLM with not authorize any mining on the site with				
2.	the exception of reclamation.  Public Safety (shafts, adits, trash, signs, highwalls)				
	The Division has received unconfirmed reports of a blast hole with explosives on site. The BLM will contact the County Sheriff to contact the person making the claim in order to find the location of the drill hole.				
3.	Protection of Drainages/Erosion Control				
4.	Deleterious Material				
5.	Roads (maintenance, surfacing, dust control, safety)				
6.	Reclamation				
	The Operator had expressed a willingness to reclaim the site in the near furture.		N/A		
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts)				
8.	Soils				
9.	Revegetation				
10.	Other				

CC: jmccarth@blm.gov

 $File: \ /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M023-Juab/S0230089\ Drumbeat1, 2, 3, 4/inspections/Insp040320151.pdf$ 



Mine: S/023/0089
Inspected: 04/03/2015
Page 2 of 2





Shallow pit where rock was extracted.



Shallow pit no evidence of mining.



Concrete pallets at the mouth of the canyon.

